



LeeGroome@aol.com  
09/14/2005 02:18 PM

To WOOD@STB.DOT.GOV.  
cc richard.streeter@BTLaw.com  
bcc  
Subject AB490 SUB#1X #35998 SERVICE DATE 8/23/05

E1-1671  
07W

MS. WOOD

PLEASE BE ADVISED ON A FEW ERRORS REPORTED TO YOU BY GREENVILLE COUNTY.

ENVIROMENTAL REVIEW STATES NO ENVIROMENTAL PROBLEM EXIST. THERE IS A RATHER LARGE POCKET OF HEXACROMINUM. IT WAS RELEASED BY US FINISHING & THEIR PREDISCOR. I KNOW SOME WORK HAS BEEN PERFORMEN, HOWEVER IT WAS STOPPED DUE TO OWNERS FININCIAL DURESS.

HISTORIC REVIEW

THIS IS IN ERROR. THE BUILDINGS OF HISTORICAL SIGNIFIANCE ARE LOCATED ON THE NORTHERN LINE NOT!! THE SOUTHERN SECTION.

I DO NOT UNDERSTAND THIS ERROR AS GREENVILLE COUNTY SPENT \$65,000 REVIEWING THE RAIL LINE AND ADJACANT PROPERTIES.

I WILL CALL YOU SHORTLY TODAY

CORDIALLY,

LEE GROOME