



Dave Geraci
Manager - Network Rationalization

EI-2972
C6

500 Water Street - J200
Jacksonville, FL 32202
Tel. (904) 359-1088
Fax (904) 359-1111
E-Mail: Dave_Geraci@CSX.com

June 7, 2007

Ms. Susan M. Pierce
Deputy State Historic Preservation Officer
West Virginia Department of Culture & History
The Cultural Center
1900 Kanawha Blvd, East
Charleston, WV 25305-0300

RE: CSXT Abandonment in Raleigh County, WV
Docket No. AB-55 (Sub-No. 661X)
FR# 05-1223-RG-2

Dear Ms. Pierce:

I received your letter dated April 24, 2007 regarding the above referenced abandonment. After speaking to Ms. Ginger Williford, I have attached the following in order to mitigate the current Section 106 condition that has been imposed by the Surface Transportation Board by decision dated October 21, 2005:

- West Virginia Historic Property Inventory Forms
- Topographic maps with the UTM locator at bridge location
- Black and white photographs of each bridge on archival paper
- Compact Disk of photographs

As further information, an on-site evaluation has found that due to an administrative error, there is no bridge structure at milepost CLP 0.20. Therefore, the information provided is for the remaining two bridges: Bridge No. 25 at Milepost CLP 2.50 and Bridge No. 33 at Milepost CLP 3.30.

Based on the information provided, I would appreciate a letter stating that the Historic Conditions have been met.

Please feel free to contact me should you have any further questions or comments.

Sincerely,

Attachments

Copy:

STB - SEA, 395 East Street, Washington, DC 20423 (w/o attachments)

Mr. Steve Armbrust, 500 Water Street - J150, Jacksonville, FL 32202 (w/o attachments)